

FIG. 1




FIG. 2A

AFTER N₂ ANNEALING




FIG. 2B

AFTER FGA+N₂ ANNEALING




FIG. 3




FIG. 4




FIG. 5




FIG. 6








FIG. 7A**FIG. 7B****FIG. 7C****FIG. 7D**




FIG. 8A**FIG. 8B****FIG. 8C**





FIG. 9A**FIG. 9B****FIG. 9C****FIG. 9D**

FIG. 10A




FIG. 10B




FIG. 10C




FIG. 11A




FIG. 11B




FIG. 12A





FIG. 12B



12/17

FIG. 13A




FIG. 13B




FIG. 14




FIG. 15




FIG. 16




FIG. 17




FIG. 18A

N₂ ANNEALING




FIG. 18B

FGA+N₂ ANNEALING

